

## Republic of the Philippines Region 1 **DIVISION OF CITY SCHOOLS DAGUPAN CITY**



Division Memorandum \_\_\_\_246\_ 2018

TO:

All School Heads/Principals

FROM:

LORNA 6. BUGAYONG Schools Division Superintendent

DATE:

April 12, 2018

SUBJECT:

**DIVISION FIRE SAFETY COMPLIANCE REPORT** 

Relative to the Annual Fire Safety Inspection conducted by the Bureau of Fire Protection Dagupan City Station in our schools, attached is the Division Compliance Report for your reference.

Kindly furnish this Division a copy of your compliance report thru the DRRM and EFU Office on or before July 6, 2018.

For your compliance.







June 28, 2018

## **CINSP GEORGIAN DM PASCUA**

City Fire Marshal Bureau of Fire Protection Dagupan City, Pangasinan

Sir:

Warm greetings from DepEd Dagupan City!

We would like to inform you that below are the actions taken on the deficiencies noted during the Fire Safety Inspection on our schools:

Defects / Deficiencies (Summary)	Remarks / Actions Taken
1. No Secondary Exit (ERB, FFCCCI, BAYANIHAN,	These bldgs were constructed from 1990s to early
DPWH, etc.)	2000 and during that time, the standard classroom
	sizes were 7m x 7m and 7m x 8m. As per NBCP,
	public facilities or structures with MORE THAN 50
	occupants must be provided with 2 sets of egress, for
	50 below 1 egress is allowed. As per consultation
	with DepEd Central Office, we were advised that
	starting 2019 Repair fund, addl. egress will be
·	included in the POW for schools in the list.
2. Inadequate / failure to maintain / absence of	Will be addressed by schools concerned.
portable fire extinguisher	
3. Dangling Electrical Wirings / Poor Installation of	- Will be addressed by succeeding DepEd Funded
Electrical Wirings / Open fuse box / uncovered	Repairs;
junction box / busted convenience outlet /	- SH to tap local electricians and be funded by School
uncovered panel board / service wire at the tree	MOOE.
4. No directional exit signs	Will be addressed by schools concerned.
5. No wet standpipe system (For multi-storey bldgs)	As per DPWH, this reqmt will be reviewed first prior
	to recommendation to Central Office (DepEd and
	DPWH) for inclusion on the succeeding New Const.
	projects. For existing buildings, review and costing
	will be done by DepED CO prior to inclusion in
	succeeding repair funds.
6. Absence of fire alarm bell	Will be addressed by schools concerned.
7. Obstructed Hallways (DCNHS)	Will be addressed by schools concerned.
8. Insufficient size of stairs.	Width of stairs is as per Approved Plans and
	Specifications set by DepEd and DPWH.

For your information.

Very truly yours,

Dr. LORMA G. BUGAYONG, CESO VI Schools Division Superintendent

